

LEE COUNTY SURVEY MARK DESCRIPTION

DESIGNATION 50 COUNTY LEE STATE FLORIDA
 LOCATED IN SEC. 31 TWP 47S RGE Z5E USGS QUAD MAP BONITA SPRINGS

TO REACH SURVEY MARK:

FROM NEW 41, RUN WEST ON BONITA BEACH ROAD TURNING NORTHERLY ONTO HICKORY BLVD. DISK IS LOCATED ACROSS FROM BONITA BEACH PARK IN THE PARKING LOT OF "CASTAWAYS RESTAURANT."

TYPE OF SET 3" LEE COUNTY PUBLIC WORKS ALUM. DISK IN PAVEMENT

MARK _____ DATE SET JUNE 7 1998

HORIZONTAL CONTROL ORIGINATED ON 2ND TRIM ORDER CONTROL BY _____

ON _____ 1927 DATUM. ON 1983 (1990 GPS ADJUSTMENT) DATUM.

COORDINATES (FT). ~~_____~~ ORDER _____ COORDINATES (FT) ~~_____~~ ORDER _____

NORTHING (Y) _____

NORTHING (Y) 726214.816

EASTING (X) _____

EASTING (X) 706888.825

GRID FLORIDA TRANSVERSE MERCATOR

RECOVERED BY _____

ZONE WEST

DATE CONDITION _____

FIELD BOOK BWL #4 PAGE 6


RECOVERY TIES

- NO. 1 $70^{\circ}-17.90'$ to Pkg. Disk (LB4919)
- NO. 2 $202^{\circ}-21.64'$ to $\frac{3}{8}$ " I.R. w/ Trav. Cap (LB4919)
- NO. 3 $285^{\circ}-22.03'$ to $\frac{5}{8}$ " I.R. w/ Trav. Cap (LB4919)

GULF OF MEXICAN

NW	NE
SW	SE

SECTION



JOHNSON ENGINEERING, INC.

CIVIL ENGINEERS - LAND SURVEYORS

2158 JOHNSON STREET, POST OFFICE BOX 1550, FORT MYERS, FLORIDA, 33902-1550

PHONE: 941-334-0046