


LEE COUNTY SURVEY MARK DESCRIPTION

DESIGNATION 50 COUNTY LEE STATE FLORIDA
 LOCATED IN SEC 31 TWP 47S RGE 25E USGS QUAD MAP BONITA SPRINGS
 TO REACH SURVEY MARK:
 FROM NEW 41, RUN WEST ON BONITA BEACH ROAD TURNING NORTHERLY
 ONTO HICKORY BLVD. DISK IS LOCATED ACROSS FROM BONITA BEACH PARK
 IN THE PARKING LOT OF "CASTAWAYS RESTAURANT."

TYPE OF SET 3" LEE COUNTY PUBLIC WORKS ALUM. DISK IN PAVEMENT
 MARK _____ DATE SET JUNE 7 1998
 HORIZONTAL CONTROL ORIGINATED ON 2ND T.M. ORDER CONTROL BY _____
 ON 1927 DATUM. ON 1983 (1990 GPS ADJUSTMENT) DATUM.
 COORDINATES (FT.) ORDER COORDINATES (FT.) ORDER
 NORTHING (Y) _____ NORTHING (Y) 726214.82
 EASTING (X) _____ EASTING (X) 706888.83
 GRID FLORIDA TRANSVERSE MERCATOR RECOVERED BY _____
 ZONE WEST DATE CONDITION _____
 FIELD BOOK BWL#4 PAGE 6



JOHNSON ENGINEERING, INC.

CIVIL ENGINEERS - LAND SURVEYORS
 2158 JOHNSON STREET, POST OFFICE BOX 1550, FORT MYERS, FLORIDA, 33902-1550
 PHONE: 941-334-0046