



Updated 2/24/2020

Alico @ Ben Hill Griffin 96 North Panel 1




- A 1-2 from Alico-Ben Hill IE5000 Gi1/14 to Port 11 ITS Express 8012 Treeline-Terminal Access
- C 5-6 from Alico-Ben Hill IE 5000 to 10 gig Terminator-x Port Te1/25
- C 11-12 from Alico-Ben Hill IE 5000 – no traffic on interface
- D 5-6 from Alico-Ben Hill IE 5000 Port Gi1/25 to Daniels-Treeline South D 5-6 to Daniels-Treeline West D 1-2 to at Hammond Stadium Main Port 12 ITS Express
- M 5-6 from Alico-Ben Hill IE5000 Port Gi1/17 to Port G1/1 IE2000 Alico-Ben Hill
- Panel H-Dark – Black Buffer given to ITG

Alico @ Ben Hill Griffin 96 West Panel 3



- A 3-4 from Alico-Ben Hill IE5000 Gi1/18 to Port 10 ITS Express 8012 Alico – I 75 NB

Alico @ Ben Hill Griffin 96 South Panel 2



- A 9-10 from Alico-Ben Hill IE5000 Port Gi1/16 to Port7 ITS Express 8040 BH & Gulf Coast
- B 1-2 from Alico-Ben Hill IE5000 Port Gi/19 to Port 12 ITS Express 8040 BH & FGCU Lakes
- E 1 – Bad fiber
- E 5-6 from Alico-Ben Hill IE5000 Port Gi1/22 to Port 9 ITS Express 8012 Corkscrew Rd and Stoneybrook
- G 5-6 from Alico-Ben Hill IE5000 Port Gi1/23 to Port G1/23 IE5000 Redundant from US 41 – Corkscrew
- G 7-8 from Alico-Ben Hill IE5000 Port Te1/28 to US\_41-Corkscrew IE 5000 Port Te1/26

Panel H-Dark – Black Buffer given to ITG