CERTIFIED CORNER RECORD

DOC. # S 1/4 Corner of Section 12 , Township 47 , Range LEE 25 County ☐ GLO CORNER (PROVEN) ☐ LAND GRANT CORNER ☐ HISTORIC CORNER ☐ OTHER CORNER CORNER DESCRIPTION: MONUMENT DESCRIPTION (EVIDENCE FOUND OR METHOD USED TO SET) Depict corner with FOUND 4x4" CONCRETE MONUMENT POST WITH BROKEN TOP, CONSISTENT WITH CORNER RECORD 081747. SEC. 12 HORIZONTAL POSITION INFORMATION (if determined): Latitude: N26° 23' 21.7615" Longitude: W81° 45' 49.2920" Y(NORTHING-Ft.) 747286.937 X(EASTING-Ft.) 733524.486 Zone FL West EXISTING NAD83(2011) Horizontal datum: **OBLITERATED** Source: ☐ LOST GPS (VRS) Determined by: S 1/4 CORNER OF SECTION 12 TWP. 47 S., RNG. 25 E. FOUND 4X4" CONCRETE MONUMENT BARBWIRE FENCE **BRKN TOP** (N = 747286.94, E = 733524.49)NOT TO SCALE 12 99° AZ 256° AZ 10.50 SET NAIL AND DISK LB #642 IN WEST FACE 4" CYPRESS TREE 149° AZ 1.00' SET NAIL AND DISK LB #642 IN NORTH SET NAIL AND DISK FACE 4" CYPRESS TREE _B #642 IN EAST FACE 6" CYPRESS TREE AZIMUTHS SHOWN ARE TO MAGNETIC NORTH Please complete sketch in black ink or type. SURVEYORS CERTIFICATE: 10/07/2017 I certify the monument and accessories indicated above were field located on SEND ORIGINAL TO: Department of Environmental Protection NOTE: Do not 4912 Bureau of Surveying and Mapping make changes to 3900 Commonwealth Boulevard PSM NO Mail Station 105 this form Johnson Engineering, Inc. 642 Tallahassee, Florida 32399 I B NO 2122 Johnson Street D.E.P. USE ONLY ADDRESS Fort Myers Florida 33901 Processed: 866-367-4400 B.L.M. - I.D. PHONE NUMBER QUAD - I.D. EMBOSSED SEAL OVER SIGNATURE

DEP 63-001(16)

REV: 01/07/14

PAGE 1 OF 1