



LEE COUNTY
SURVEY MARK DESCRIPTION

DESIGNATION 5526 COUNTY Lee STATE FL
LOCATION IN SEC 1 TWP 46 S. RGE 22 E. USGS QUAD MAP Pine Island Center, Fla
TO REACH SURVEY MARK:

TYPE OF 3 1/4" Aluminum Lee County Survey Control Mark Set in Concrete
MARK 5526 DATE SET Feb. 1999

HORIZONTAL CONTROL ORIGINATED ON 2nd/1ST ORDER CONTROL BY National Geodetic Survey (NGS)
ON 1927 DATUM. ON 1983 (1990 GPS Adj.) DATUM.
COORDINATES (FT), 2nd ORDER COORDINATES (FT), 2nd ORDER
NORTHING (Y) N/A NORTHING (Y) 787778.526
EASTING (X) N/A EASTING (X) 633662.866
GRID Florida Transverse Mercator RECOVERED BY _____
ZONE West DATE, CONDITION _____
FIELD BOOK 4 PAGE(S) 15

RECOVERY TIES:



NW	NE
SW	SE

SECTION 1

SCALE: N.T.S.

SKETCH BY SAW

JOHNSON ENGINEERING, INC.

ENGINEERS, SURVEYORS AND ECOLOGISTS

215R JOHNSON STREET, POST OFFICE BOX 1550, FORT MYERS, FLORIDA 33902-1550, PHONE (941) 334-0046