



Daniels @ Six Mile Cypress 96 North Panel 2




- A 1-2 to Panel 1 K 1-2
- B 1-2 to Panel 3 B 1-2
- C 5-6 to Panel 3 C 3-4
- C 11-12 to Panel 3 C 4,8
- F 1-2 Unreliable probably pinched south of Dani Dr
- F 3-4 to West Panel 1 F 1-2

Daniels @ Six Mile Cypress 96 West Panel 1



- F 1-2 to Panel 2 F 1-2
- K 1-2 to Panel 2 A 1-2

Daniels @ Six Mile Cypress 96 East Panel 3



- B 1-2 to Fiber Patch Panel 2 B 1-2
- C 4,8 to Panel 2 C 11-12
- C 5-6 to Panel 2 C 5-6
- Black Buffer Tube to ITG