


Phase 1 & 2 Flood Assessment

Type of Observation

- Damaged Structure
- Debris
- Erosion
- High Water Indicator
- Inspected Area
- Sediment
- Vegetation
- Other



North
Fort
Myers

Lehigh Acres

Whiskey
Creek

South
Fort
Myers

SE Lee County